

i.LON 600

LAST UPDATE: 06 JUN 2011
PART NUMBER: 153-0377-01A

This service pack adds the following items to the i.LON 600:

- Standalone Echelon IP-852 Configuration Server
- 64-bit Windows Compatibility
- Other problem fixes and new Network Diagnostics

This service pack also includes all fixes from Service Packs 2, 3, 4, 5 and 6.



Warning: The firmware and bootrom image in this service pack cannot be used with i.LON 600s manufactured after November 2015. If this bootrom image or firmware image is loaded in an i.LON 600 manufactured after November 2015, the i.LON 600 will become inoperable and cannot be recovered.

Software Downloads

This service pack also includes all fixes from Service Packs 2, 3, 4, 5 and 6.

- [i.LON 600 Release 1.0 Service Pack 7](#)
 - [ReadMe](#)